


## Engine + gearbox skid plate

## 2111.2730.1.3

Brand	Model	Year	Engine	Gearbox	Drive
Jeep	Wrangler	2007-	2,8d	Manual	Full
		Left bracket OE fitting			







## Installation Instructions:

- 1.Remove OE transfer case protection and cross beam.
  2.Mount left and right brackets using OE fittings (A).
  3.Mount beam on OE holes using OE fittings through the spacer on the left side (B) and (C).
  4.Mount countersunk nut over the hole in chassis (D) And screw in bolt M10x40 for a 2-3. turns.
- 5. Screw in OE fittings for a few turns (E).
- 6. Mount skid plate: rear part mount on installed bolts, front part mount on brackets using bolts M10x30, middle part mount on beam using bolts M10x30 (F).
- 7. Tighten all screws with required torque.

Name QTY Torque  1.Bolt M10x30 5 pcs. 47.0 Nm 2.Bolt M10x40 1 pc. 47.0 Nm 3.Washer 10 6 pcs. 4.Washer spring 10 6 pcs. 6.Countersunk nut M10x100/50 1 pc. 6.Left bracket 7.Right bracket 7.Right bracket 8.Beam 9. Spacer 1 pc.	Content:		
2.Bolt M10x40	Name	QTY	Torque
	2.Bolt M10x40 3.Washer 10 4.Washer spring 10 5.Countersunk nut M10x100/50 6.Left bracket 7.Right bracket	1 pc. 6 pcs. 6 pcs. 1 pc. 1 pc. 1 pc. 1 pc.	